



**US Army Corps
of Engineers®**

Detroit District
P.O. Box 1027
Detroit, MI 48231-1027
(313) 226-6797
FAX - (313) 226-3519

Notice to Navigation Interests

Notice No. L06-25

Date: 15 JUNE 2006

Waterway: LAKE HURON

Location: MICHIGAN

CELRE-OT-T

CONDITION OF FEDERAL NAVIGATION CHANNEL LEXINGTON HARBOR

1. Surveys performed within the Federal navigation channel at Lexington Harbor, Michigan during June 2006, indicate shoaling as shown on the back of this sheet.
2. Mariners are urged to use extreme caution in the area.
3. All inquiries should be addressed to CELRE-OT-T and should refer to Notice to Navigation Interests No. L06-25. Internet address: <http://www.lre.usace.army.mil> Go to: Detroit Home Page, Who We Are, Operations Office Home Page.

DONALD P. LAUZON
Lieutenant Colonel, U.S. Army
District Engineer


Notice to the Postmaster:

It is requested that the above notice be conspicuously and continuously posted until November 30, 2006.



Shoals indicate least available
depth below LWD

LAKE HURON



THE INFORMATION DEPICTED
ON THIS DRAWING
REPRESENTS THE RESULTS
OF SURVEYS MADE ON THE
DATES INDICATED AND CAN
ONLY BE CONSIDERED AS
INDICATING THE GENERAL
CONDITIONS EXISTING AT
THAT TIME.

ELEVATIONS AND PROJECT
DEPTHS ARE REFERRED TO
IGLD, 1985 WHEN LAKE HURON
IS AT ELEVATION 577.5 FT.
ABOVE MEAN WATER LEVEL
AT RIMOUSKI, QUEBEC.

SURVEYED: June 2006

LEXINGTON HARBOR, MI

CONDITION OF CHANNEL

ISSUED: 15 June 2006

U.S. Army Engineer District, Detroit